GOLF COURSE EQUIPMENT LIST/ REPLACEMENT COST

| | А | В | С | D | Е | F |
|--------------|------------------------------------|----------|----------|-------------|--------|-----------|
| 1 | | Date | | Replacement | Age | Condition |
| 2 | Equipment | Acquired | Cost | Cost | (Yrs.) | |
| 3 | | | | | | |
| 4 | Fairway Mower (2011) | 2016 | \$22,000 | \$45,000 | 9 | Fair/good |
| 5 | | | | | | |
| 6 | Rough Mower (2010) | 2017 | \$18,500 | \$60,000 | 10 | Fair/good |
| 7 | | | | | | |
| - | Banks Mower (2012) | 2017 | \$11,500 | \$35,000 | 8 | Fair/good |
| 9 | | | | | | |
| - | Greens Mower (2014) | 2019 | \$12,000 | \$30,000 | 6 | Good |
| 11 | | | | | | |
| | Tees Mower (2010) | 2019 | \$6,950 | \$30,000 | 10 | Fair/good |
| 13 | | | | 4 | | |
| | Kubota (1999) | 2000 | ? | \$40,000 | 20 | Fair |
| 15 | | 2020 | 1.0000 | 427.000 | _ | |
| - | Large utility/Toro Workmen (2015) | 2020 | 16000 | \$27,000 | 5 | Good |
| 17 | 111111 1:1 / T (11 / 2042) | 2020 | 4050 | Ġ0.000 | 0 | C I |
| - | Utility vehicle/ Turf II (2012) | 2020 | 4959 | \$9,000 | 8 | Good |
| 19 | Httlity Vahiala (Carayar/1006) | 1000 | | ¢3E 000 | 24 | Door |
| 20 | Utility Vehicle/Sprayer(1996) | 1998 | | \$35,000 | 24 | Poor |
| - | Bunker Rake (2000) | 2005 | \$5,000 | \$15,000 | 19 | Poor |
| 23 | Bullker Nake (2000) | 2003 | 33,000 | \$13,000 | 19 | FOOI |
| \vdash | Out front Mower (1990) | 2014 | \$1,800 | \$25,000 | 29 | Poor |
| 25 | out none mower (1990) | 2011 | 71,000 | 723,000 | 23 | 1 001 |
| | Irrigation system | | | | | |
| | Irrigation system (early 1980s?) | | | \$75,000 | 40+ | |
| | Pump replacement | 2020 | \$25,000 | | | Good |
| \mathbf{H} | Auxiliary pump, pump house repairs | 2021 | \$25,000 | | | Poor |
| 30 | Controls, piping, heads Revisions | Future | | | | Poor |
| 31 | | | | \$426,000 | | |